

Tutorial B1.1. Eobody2 Universal Board Wiring



1 connecting a switch to a digital input



2 connecting potentiometers and other analogue sensors to analogue inputs



1 to signal
1 to 5Volt
1 to the ground

eowave©2007-2008 All Rights Reserved. info@eowave.com www.eowave.com